

Comments Screen Inquiry Mode - -

File Edit Functions Help

Comments Screen Inquiry Mode

Equip Type	MTRE	Equip ID	2513903
Date	2026/01/13 17	Op Code	TEST

HISTORY RECORD ADDED ; METER TESTED OK

OK Cancel

Electric Meter Test Results - Screen One - MTR01 - ***NOVA SCOTIA POWER IN...

FileEditFunctionsHelp

Electric Meter Test Results - Screen One

Equip Type	MTRE	Date	2026/01/1317
Equip ID	2513903	Op Code	TEST
Tester's User ID	AG431		
Standard Code			
As Found kWh	11954.00		
Lot Number			
Damage Code			
Firmware Version			
OTHER			

Next Screen

Delete

OK

Cancel

Electric Meter Test Results - Screen Two - MTR02 - ***NOVA SCOTIA POWER IN...

FileEditFunctionsHelp

Electric Meter Test Results - Screen Two

Equip Type

MTRE

Equip ID

2513903

Date

2026/01/1317

Op Code

TEST

FLSASFKWH

+0.08

FLAASFKWH

FLCASFKWH

FLBASFKWH

LLSASFKWH

+0.01

LLAASFKWH

LLCASFKWH

LLBASFKWH

PFSASFKWH

+0.03

PFAASFKWH

+0.11

PFCASFKWH

+0.10

PFBASFKWH

FLSASFKQH

FLAASFKQH

FLCASFKQH

FLBASFKQH

LLSASFKQH

LLAASFKQH

LLCASFKQH

LLBASFKQH

PFSASFKQH

PFAASFKQH

PFCASFKQH

PFBASFKQH

Next Screen

Delete

OK

Cancel

Electric Meter Test Results - Screen Three - - *** NOVA SCOTIA POWER INC. *... — □ ×

File Edit Functions Help

Electric Meter Test Results - Screen Three

Equip TypeMTRE

Equip ID2513903

Date2026/01/1317

Op CodeTEST

FLSASLKWH		FLSASLKQH		FLAASLKWH	
FLAASLKQH		FLCASLKWH		FLCASLKQH	
FLBASLKWH		FLBASLKQH		LLSASLKWH	
LLSASLKQH		LLAASLKWH		LLAASLKQH	
LLCASLKWH		LLCASLKQH		LLBASLKWH	
LLBASLKQH		PFSASLKWH		PFSASLKQH	
PFAASLKWH		PFAASLKQH		PFCASLKWH	
PFCASLKQH		PFBASLKWH		PFBASLKQH	
PULASLKWH		PULASLKVA		PULASLKQH	
REGRATIO	DIG	CRCHECK		LOSSCOMP	

Next Screen

Delete

OK

Cancel

Electric Meter Test Results - Screen Four - - *** NOVA SCOTIA POWER INC. ***

File Edit Functions Help

Electric Meter Test Results - Screen Four

Equip Type	MTRE	Date	2026/01/1317
Equip ID	2513903	Op Code	TEST

Creep Test Performed	☒	Replaced Base	☐
Dial Check Performed	☒	Replaced Cover	☐
Phase Test Performed	☐	Replaced Register	☐
Short Test Performed	☐	Replaced Idle Pointe	☐
Hand Test Performed	☒	Replaced Battery	☐
Replace Up Bearing	☐	Replaced Thermal elm	☐
Replace Lower Bearin	☐	As Left kWh	11956.00
Replaced Disk	☐		

Delete

OKCancel